# Material Safety Data Sheet X-9032/G401 Nix Stix® Mold Release



Copying and/or downloading of this information for the purpose of properly utilizing Stoner Inc., product is allowed provided that: (1) the information is copied in full with no changes unless prior agreement is obtained from Stoner Inc., & (2) neither the copy nor the original is resold or otherwise distributed with intention of earning profit thereon.

1. (	CHEMICAL	PRODUCT AN	D COMPANY	<b>IDENTIFICATION</b>
------	----------	------------	-----------	-----------------------

Stoner Incorporated 1070 Robert Fulton Hwy. Quarryville, PA 17566 1-800-227-5538 Product Name: Product Code: Version Date: 24-hour emergency phone: Nix Stix® Mold Release X-9032/G401 12/24/14 1-800-424-9300 [CHEMTREC]

## 2. COMPOSITION / INFORMATION ON INGREDIENTS

				Exposure Limits				
COMPONENT		<u>CAS #</u>	ACGIH TLV	OSHA PEL	<b>OTHER</b>			
	/drocarbon/ether blend	Mixture	Not established	Not established	1000ppm TWA (Mfr.)			
NJ Trade Secre	t Registry	#80100382-5152P	Not established	Not established	800 ppm Manf. estb.			
3. HAZAH	RDS IDENTIFICATIO	)N						
POTENTIAL A	ACUTE [single or short term	] HEALTH EFFECTS OF	OVEREXPOSURE					
Eye :	May cause eye irritation. Symptoms may include stinging, tearing, and redness.							
Skin :		Liquid may cause frostbite. Prolonged or repeated exposure may dry the skin. Skin contact may cause irritation. Symptoms may include						
				body through the skin is po	ssible, but it is unlikely that			
T		ul effects during safe handling		G11				
Ingestion :		Swallowing small amounts during handling is not likely to cause harmful effects. Swallowing large amounts may be harmful. This material can enter the lungs during swallowing or vomiting and cause lung inflammation and/or damage.						
Inhalation :					be harmful Inhalation of			
initiation .		Breathing small amounts during handling is not likely to cause harmful effects. Breathing large amounts may be harmful. Inhalation of concentrations above the recommended limits may cause temporary central nervous system depression with anesthetic effects such as						
		dizziness, headache, incoordination, and loss of consciousness. Exposure to high concentrations can cause irregular heartbeat, cardiac arrest						
	and death. Symptoms are	and death. Symptoms are more typically seen at air concentrations exceeding the recommended exposure limits. Symptoms of exposure may						
		include: initial Central Nervous System excitation (euphoria, exhilaration, light-headedness) followed by CNS depression (dizziness,						
		igue, nausea, headache, unco	onsciousness) and other CNS	5 effects, such as confusion,	impaired coordination, coma,			
	and death.							
	CHRONIC [long term] HEA							
General Effect		1		nponents) has been suggest	ed as a cause of the following			
Cancer Inform		bry animals: effects on hearing		NOCENIC DV LADC NT				
Mutagenicity:	Contains no muta		NENTS LISTED AS CARC	INOGENIC BY IAKC, NT	P, OR OSHA 1910(Z)			
	ONDITIONS AGGRAVATE							
			cular system may have incre	eased susceptibility to the to	xicity of excessive exposures.			
	AZARDOUS WARNINGS:				·····, ····			
Health: 2	Flammability:	2 Physical:	1 Personal	Protective Equipment: Se	ee Section 8			
* See www.pair	nt.org/hmis or call the NPCA	at 1 (202) 462-6272 for mor	e information on this curren	t rating system.				
4. FIRST	AID MEASURES							
Eyes:			for at least 15 minutes while	holding eyelids apart. If sy	mptoms persist or there is			
	visual difficulty, seek n							
Skin Contact:	In case of contact, imm	ediately wash contaminated	area with plenty of water for	r at least 15 minutes. Seek n	nedical attention if			

Skin Contact:	In case of contact, immediately wash contaminated area with plenty of water for at least 15 minutes. Seek medical attention if
	symptoms persist. Seek medical attention if symptoms persist. Wash clothing before reuse. For liquid contact, treat for frostbite if
	necessary.
Ingestion:	Do not induce vomiting. Aspiration into the lungs can cause serious damage. If vomiting occurs spontaneously, keep head below hip

 Ingestion:
 Do not induce vomiting. Aspiration into the lungs can cause serious damage. If vomiting occurs spontaneously, keep head below hips to prevent aspiration of liquid into lungs. Contact a physician, medical facility, or poison control center immediately.

 Inhalation:
 Remove to fresh air. If not breathing, give artificial respiration. If breathing is difficult, give oxygen. Seek immediate medical attention.

NOTES TO PHYSICIAN:

Because of possible disturbances of cardiac rhythm, catecholamine drugs, such as epinephrine, should be used only in situations of emergency life support. Treatment is symptomatic and supportive. This material is an aspiration hazard. Potential danger from aspiration must be weighed against possible oral toxicity when deciding whether to induce vomiting. Preexisting disorders of the following organs (or organ systems) may be aggravated by exposure to this material: skin; lung (for example, asthma-like conditions); kidney; central nervous system; auditory system; arrhythmias (irregular heartbeats);

# 5. FIRE FIGHTING MEASURES

Stoner Incorporated	X-9032/G401 PA	GE 1
Flash Point:	Not applicable°F PMCC	°C PMCC
	1 11 1	pressure self-contained breathing apparatus. Avoid breathing the products and e thermal decomposition of the product or other substances in the fire zone.
The Fighting instructions.	used from a safe distance to cool c	losed containers and protect surrounding area. Fire fighters should wear normal
Fire Fighting Instructions:		rmed (see Sec.10). "Empty" containers retain product residue and can be dangerous. <i>J</i> ater is generally not effective and may spread fire; however, water spray may be
		g point.Containers may rupture or explode under fire conditions. Hazardous
	2	tion and ignited by heat, pilot lights, or other flames and ignition sources at locations
	1 ()	flammable liquid, which has vapors that are heavier than air and may travel along
	e	tions distant from the material's handling point. This product contains a
	heavier than air and may travel alo	ng the ground or be moved by ventilation and ignited by heat, pilot lights, or other
Fire and/or Explosion Hazards:	This product contains a component	t(s) that is considered an extremely flammable gas(es), which has vapors that are

Lower Flammability Limit:	Not applicable
Upper Flammability Limit:	Not applicable
Autoignition Temperature:	Not applicable <sup>o</sup> F
Aerosol Flame Projection Test:	Non-flammable aerosol, as determined by ASTM D3065-94. However, this product contains components which may
	be ignited under certain circumstances. Do not use near ignition sources such as sparks or open flames.

#### 6. ACCIDENTAL RELEASE MEASURES

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED:

Ventilate contaminated area. Remove all sources of ignition. Wear appropriate personal protective equipment (PPE). Stop or reduce discharge if it can be done safely. Avoid run-off into storm sewers and ditches which may lead to natural waterways. Clean up with absorbent material. Place absorbent materials into container and close it tightly. Dispose of container properly. If runoff occurs, notify authorities as required.

#### 7. HANDLING AND STORAGE

Handling: Use with adequate ventilation. Do not use near ignition sources. Avoid prolonged or repeated contact with skin. Avoid prolonged or repeated breathing of vapor. Normal precautions common to safe manufacturing practice should be followed in handling and storage. This material can be harmful or irritating. Do not pressurize, cut, weld, braze, solder, drill, grind, or expose such containers to heat, flame, sparks, static electricity, or other sources of ignition; they may explode and cause injury or death.

Storage: Store in a cool, dry, well ventilated area away from all sources of ignition. Do not store at temperatures above 120 degrees F. Empty container may contain residues which are hazardous. Store away from incompatible materials such as materials that support combustion (oxidizing materials) and corrosive materials (strong acids or bases). Store away from oxygen cylinders or other oxidizing materials and possible ignition sources. Ground all equipment and cylinders before use. Store away from heat and direct sunlight. Normal precautions common to safe manufacturing practice should be followed in handling and storage.

## 8. EXPOSURE CONTROLS / PERSONAL PROTECTION

Engineering Controls:	Ventilation should be adequate to prevent exposures above the limits indicated in "Section 2" of this MSDS (from known, suspected or apparent adverse effects).
Eye Protection:	Wear chemically resistant safety glasses with side shields when handling this product. Wear additional eye protection such
	as chemical splash goggles and/or face shield when the possibility exists for eye contact with splashing or spraying liquid or airborne material. Do not wear contact lenses. Have an eye wash station available.
Skin Protection:	The use of chemically resistant gloves is recommended if there is any possibility of prolonged or repeated liquid contact with skin.
Respiratory Protection:	A supplied air respirator should be used if ventilation is not sufficient to maintain exposure limits. Use NIOSH approved respirator where there is likelihood of inhalation of the product mist, spray or aerosol.

## 9. PHYSICAL AND CHEMICAL PROPERTIES

Physical State:	Aerosol can	Vapor Density:	[air = 1] 2.26
Appearance:	Clear Colorless	Evaporation Rate:	0.1-0.5 (n-Butyl acetate = 1)
Odor:	Slight ethereal.	Solubility in Water:	Not determined
Specific Gravity:	0.84 (H2O=1)	Boiling Point:	No data available°F
Vapor Pressure:	87.00 PSIG @ 70°F	pH:	Not applicable

## 10. STABILITY AND REACTIVITY

Chemical Stability:	Stable.
Conditions to Avoid:	Avoid contact with: Alkali. Alkaline earth metals. Freshly abraded aluminum surfaces. Powdered metals. Ignition sources such as open flames, sparks, static discharges or glowing metal surfaces. Oxidizers. Acetic acids Organic acid anhydrides. Sparks, open flame, other ignition sources, and elevated temperatures. Can form a combustible mixture with air at pressures above atmospheric pressure. Do not mix with oxygen or air above atmospheric pressure. Strong oxidizing agents.
Decomposition Products:	This material can be decomposed by extremely high temperatures (open flames, glowing metal surfaces, etc.) forming hydrofluoric acid and carbonyl fluoride. If heated with peroxides present, violent decomposition can occur. Burning can produce the following combustion products: Carbon dioxide and carbon monoxide. Hydrogen chloride. Hydrogen Chloride. Various hydrocarbons.

## 11. DISPOSAL CONSIDERATIONS

Disposal : Dispose according to Federal, State and local regulations.

#### 12. TRANSPORTATION INFORMATION

Agency	Proper Shipping name	UN Number	Hazard Class	Packing Group
DOT	Aerosols, Non- Flammable <sup>†</sup>	UN1950	2.2	Not applicable
IATA	Aerosols, Non- Flammable†	UN1950	2.2	Not applicable
IMDG	Aerosols, Non- Flammable <sup>†</sup>	UN1950	2.2	Not applicable
† "Limited	Quantities" may be applicable for this transport	ortation mode.		
13. REC	GULATORY INFORMATION			

 COMPONENT
 CAS #
 % BY WEIGHT
 Regulatory Body

 No components listed in this section.
 \$\$ARA Section 313

Warning: This product may contain chemicals known to the State of California to cause cancer. See list below. No components listed in this section. Prop65 Cancer

Warning: This product may contain chemicals known to the State of California to cause birth defects. See list below. No components listed in this section. Prop65 Birth Defects All components of this product are listed on the TSCA inventory.

This information contained in this MSDS is believed to be accurate as of the version date, but is not warranted to be. Since the use of this information and the conditions of use of this product are not within the control of Stoner Inc, it is the user's obligation to determine the conditions of safe use.